



David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

April 24, 2018

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Customer Satisfaction Program 18M01

Certain 2011-2012 Model Year F-250-F-550 and 2013-2015 F-450-F-550 equipped with a 6.7L Diesel Engine
Reductant Heater and Sender Assembly Repair

PROGRAM TERMS

This program extends the warranty coverage of the reductant heater and sender assembly to 11 years of service or 120,000 miles from the warranty start date of the vehicle, whichever occurs first. If a vehicle has already exceeded either the time or mileage limits, this extended warranty coverage will last through December 31, 2018. Coverage is automatically transferred to subsequent owners.

NOTE: This program does not apply to vehicles that qualify for repairs under the New Vehicle Limited Warranty. Repairs for vehicles covered by New Vehicle Limited Warranty should be claimed using existing published labor operation codes.

VEHICLES COVERED BY THIS PROGRAM

Vehicle	Model Year	Assembly Plant	Build Dates
F-250 - F-550	2011-2012	Kentucky Truck	August 24, 2009 through October 23, 2012
F-450 - F-550	2013-2015	Kentucky Truck	April 16, 2012 through December 9, 2014

Affected vehicles are identified in OASIS.

REASON FOR PROVIDING EXTENDED WARRANTY COVERAGE

In some of the affected vehicles, the reductant heater and sender assembly may fail causing the malfunction indicator lamp (MIL) to illuminate and, in some instances, may cause the engine to go into a reduced power de-rate strategy. If this condition exists, diagnostic trouble codes (DTCs) related to the reductant heater and sender assembly will be present in the powertrain control module.

SERVICE ACTION

If an affected vehicle exhibits this condition, dealers are to service the reductant heater and sender system following the instructions in the technical information section of this bulletin. This service must be performed at no charge to the vehicle owner.

OWNER NOTIFICATION MAILING SCHEDULE

Owner Letters are expected to be mailed the week of June 25, 2018. Dealers should repair any affected vehicles that have the MIL illuminated with DTC's related to the reductant heater and sender assembly whether or not the customer has received a letter.


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Owner Notification Letter

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Johnson", written in a cursive style.

David J. Johnson

Customer Satisfaction Program 18M01
Certain 2011-2012 Model Year F-250-F-550 and
2013-2015 F-450-F-550 equipped with a 6.7L Diesel Engine
Reductant Heater and Sender Assembly Repair

OASIS ACTIVATION

OASIS will be activated on April 24, 2018.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will not be activated for this service action.

SOLD VEHICLES

- Only owners with affected vehicles that exhibit the covered condition will be directed to dealers for repairs.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

STOCK VEHICLES

- Do not perform this program unless the affected vehicle exhibits the covered condition.

TITLE BRANDED / SALVAGED VEHICLES

Title branded, salvaged vehicles and vehicles with cancelled warranty coverage are eligible for this program unless emission coverage is explicitly cancelled, as indicated by one of the following OASIS Warranty Cancellation Messages only:

- SCRAPPED UNIT – ALL WARRANTY CANCELLED – TOTAL INCLUDING EMISSIONS
- ALL WARRANTY CANCELLED INCLUDING EMISSIONS

OWNER REFUNDS

- Ford Motor Company is offering a refund for owner-paid repairs covered by this program if the repair was performed before the date of the Owner Notification Letter. This refund offer expires December 31, 2018.
- Dealers are also pre-approved to refund owner-paid emergency repairs that were performed away from an authorized servicing dealer after the date of the Owner Notification Letter. There is no expiration date for emergency repair refunds. Non-covered repairs, or those judged by Ford to be excessive, will not be reimbursed.
- Refunds will only be provided for the cost associated with replacing the reductant heater and sender assembly.

RENTAL VEHICLES

The use of rental vehicles is not approved for this program.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual – Section 6 – Ford/Lincoln Program Policies – Field Service Actions (FSA) – Related Damage.
- For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required.
 - Ford vehicles – 3 years or 36,000 miles
- For vehicles outside new vehicle bumper-to-bumper warranty coverage, submit an Approval Request to the SSSC Web Contact Site prior to completing the repair.

Customer Satisfaction Program 18M01

Certain 2011-2012 Model Year F-250-F-550 and
2013-2015 F-450-F-550 equipped with a 6.7L Diesel Engine
Reductant Heater and Sender Assembly Repair

CLAIMS PREPARATION AND SUBMISSION

- This program does not apply to vehicles that qualify for repairs under the New Vehicle Limited Warranty. Repairs for vehicles covered by New Vehicle Limited Warranty should be claimed using published labor operation codes.
- Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims, select claim type 31: Field Service Action. The FSA number (18M01) is the sub code.
 - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- Additional labor and/or parts must be claimed as related damage on a separate repair line from the FSA. **IMPORTANT:** Click the radio button on the Related Damage Indicator.
- Submit refunds on a separate repair line.
 - Program Code: 18M01
 - Misc. Expense: ADMIN
 - Misc. Expense: REFUND
 - Misc. Expense: 0.2 Hrs.
- Multiple refunds should be submitted on one repair line and the invoice details for each repair should be detailed in the comments section of the claim.

Customer Satisfaction Program 18M01
 Certain 2011-2012 Model Year F-250-F-550 and
 2013-2015 F-450-F-550 equipped with a 6.7L Diesel Engine
 Reductant Heater and Sender Assembly Repair

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
<u>2011-2014 Super Duty (All Configurations)</u> Reprogram the PCM using IDS release 109.01 or higher. No other repairs needed.	18M01B	0.7 Hours
<u>2011-2014 Super Duty Pickup</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01C	1.9 Hours
<u>2011-2014 Chassis Cab – Inboard Reductant Tank</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01D	1.8 Hours
<u>2011-2014 Chassis Cab – Outboard Reductant Tank</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01E	1.5 Hours
<u>2015 Super Duty (All Configurations)</u> Reprogram the PCM using IDS release 109.01 or higher. No other repairs required.	18M01F	0.4 Hours
<u>2015 Super Duty Pickup</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01G	1.6 Hours
<u>2015 Chassis Cab – Inboard Reductant Tank</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01H	1.6 Hours
<u>2015 Chassis Cab – Outboard Reductant Tank</u> Replace the reductant heater and sender assembly and reprogram the PCM using IDS release 109.01 or higher	18M01J	1.3 Hours

Extra time to R&I fuel tank shield (if equipped) to access lifting points

Vehicle	Labor Operation	Labor Time
Non-FX4 package vehicles	18M01K	0.1
FX4 package vehicles only	18M01L	0.3

Customer Satisfaction Program 18M01
Certain 2011-2012 Model Year F-250-F-550 and
2013-2015 F-450-F-550 equipped with a 6.7L Diesel Engine
Reductant Heater and Sender Assembly Repair

PARTS REQUIREMENTS / ORDERING INFORMATION

Less than 14% of the vehicle population covered by this program is expected to require reductant heater and sender assembly replacement.

Part Number	Description	Order Quantity	Claim Quantity
BC3Z-5J225-L	Reductant Heater and Sender Assembly (Pickup)	1	1
BC3Z-5J225-M	Reductant Heater and Sender Assembly (Chassis Cab)	1	1
PM-27*	Motorcraft Diesel Exhaust Fluid	Up to 5 gallons	

*The use of PM-27-GAL, PM-27-JUG, PM-27-D, or PM-27-T is acceptable.

The DOR/COR number for this recall is 51121.

Order your parts through normal order processing channels. To guarantee the shortest delivery time, an emergency order for parts must be placed.