

Technical Bulletin #620



4R44E, 4R55E, 5R55E

Delayed Forward Engagement

To improve forward engagement, remove the spring from the engagement control valve.



BB #620♦ Page 1 of 1