



Technical Bulletin #491

Transmission: 4R55E / 5R55E

Subject: *Delayed engagement in drive*

Application: *Ford*

Issue Date: *December, 1998*

4R55E / 5R55E

Delayed Engagement in Drive

Delayed engagement in drive or no engagement in D4 or D3, but okay in manual 1 and manual 2. To correct these conditions simply remove the spring at engagement control valve.

